

IMPORTANT SAFETY NOTICE

Lennox Industries Separated Combustion Gas-Fired Unit “Garage” Heaters

Some heaters identified below were mistakenly manufactured without a required “flame rollout switch,” which is a backup device designed to shut down the heater and prevent a fire in the event of certain types of heater failures. No reports of incident or injury have been received.

Heating Capacity	Model Number	Serial Number Range	Dates of Possible Sale
60,000 BTUH	TUA060SNAF1	5609H##### to 5610M#####	Aug 2009 - April 2011
100,000 BTUH	TUA100SNAF1	6004G##### to 6010L##### 5604G##### to 5610L#####	July 2004 - April 2011
100,000 BTUH	TUA100SNSF1	6004G##### to 6010L##### 5604G##### to 5610L#####	July 2004 - April 2011
125,000 BTUH	TUA125SNAF1	6004G##### to 6010L##### 5604G##### to 5610L#####	July 2004 - April 2011
125,000 BTUH	TUA125SNSF1	6004G##### to 6010L##### 5604G##### to 5610L#####	July 2004 - April 2011



Affected heaters will be inspected and repaired, if necessary, free of charge.

For information, call Lennox Industries toll-free at (888) 584-2353 between 8 a.m. and 5 p.m. CT Monday through Friday, or visit www.lennox.com.