



REMOVE EXISTING WIRES "K10-7" AND "K10-9" FROM RELAY CONNECTOR ON THE K10 RELAY. LOOSE WIRES MUST BE PROPERLY ISOLATED TO PREVENT AN ELECTRIC SHOCK HAZARD.

A188	TRANSDUCER, COMPRESSOR STAGE 1		
A189	TRANSDUCER, COMPRESSOR STAGE 2		
A190	CONTROL, HEAD PRESSURE		
B1	COMPRESSOR 1		
B2	COMPRESSOR 2		
B4	MOTOR, OUTDOOR FAN 1		
B5	MOTOR, OUTDOOR FAN 2		
K1	CONTACTOR, COMPRESSOR 1		
K2	CONTACTOR, COMPRESSOR 2		
K10	RELAY, OUTDOOR FANS		

4 F. 3.1 P. 2	WIRING DIAGRAM		04/24	
	538038-02			
COOLING				
KC/KGB - 092, 102, 120S - G, J, M, Y				
SECTION B			EV. 1.0	
Supersedes	New Form No.			
538038-01	538038-0	12		
<u> </u>				

© 2009 Lennox Commercial