

## COMMERCIAL TRAINING TOOLBOX TIPS

### Blower Bearing Set Screws


Applies to Lennox Energence, Strategos, Landmark, and Raider Rooftop Units 3-6 tons

#### Helpful Resources

1. [Lennoxcommercial.com](http://Lennoxcommercial.com) or [LennoxPros.com](http://LennoxPros.com)

Some 3 to 6-ton Energence, Strategos, Landmark, and Raider units may have blower bearing set screws which did not receive the full specified torque of 80-inch pounds, beginning with July 2020 production of these units thru April 2021. Serial numbers begin with 5620FXXXXX to 5621DXXXXX.

Lennox recommends checking these set screws for tightness as part of the initial unit start up and during seasonal maintenance checks.



MORE Training Toolbox Tips Available!  
Click [here](#) to download them all.

Self-Service Technical Support with No  
Wait Times! Click the black logos to  
download these apps.



Click [here](#) to register for any of the  
Lennox Commercial Product Technical  
Training Webinars.